

### Brown & Sharpe Angle Gauges

For setting and calibration purposes – Smallest step to 15' (1/4°).



Width:  
6,35 mm (1/4 in)  
Length:  
≥ 76,2 mm (3 in)



06769002 Precision angle block set

Set Composition  
15' / 30' / 1° / 2° / 3° / 4° / 5° /  
10° / 15° / 20° / 25° / 30°

### Steel Balls – Brown & Sharpe Steel Balls

Steel balls are used to measure internal tapers and similar.



06769009 Steel ball set

mm

Step, mm

Pieces by Nominal Ø /total pieces

1 ÷ 25

1

2 / 50

