

Measuring stands

- Clamping shaft: $\varnothing 8$ mm.
- Transverse arm with fine adjustment.
- Arm length: 150 mm.
- Ground base.
- Base with V-groove (only 857.120).



857.120




857.121

Item No.	Column \varnothing /mm	Dimensions base/mm	Effective arm length/mm
857.120	16	65 x 40 x 140	250
857.121	22	60 x 55 x 250	300

Measuring stand

- Clamping shaft: $\varnothing 8$ mm.
- Effective arm length: 180 mm.
- Fine adjustment.
- Ground base with V- and T-groove, 250 x 60 x 35 mm.
- Column: $\varnothing 16$ x 295 mm.
- Arm: $\varnothing 16$ x 235 mm.
- Mechanical clamping device.
- Dial indicator not included.



Dimensions T-groove

Item No.	Description
856.720	Measuring stand